



BMW 5 TOURING: 1KXA279			
Vinnumber:	WBA5L11090D786159	Versionname:	2.0 518D (100KW) TOURING
First Registrationdate:	17/07/2015	Fiscalpower:	
Expertise Mileage:	96480	Power Kw:	100
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2432
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Level control	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	225/55/17/95 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT		2661,53	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00	



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Dirty, Cleaning 100,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 369,84



Air vent R M, Strained , E - Replace 158,40



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Seat cover F L, Hole, Smart repair 64,32



Wing R L, Bump(s) and scratch(es), Le - Replace and paint 1429,81

