


BMW X1: 1GQQ950

| | | | |
|------------------------------------|--------------------------|--------------|---------------------------|
| Vinnumber: | WBAVY11060VZ24316 | Versionname: | X1 sDrive16d 116PK |
| First Registrationdate: | 2/04/2014 | Fiscalpower: | |
| Expertise Mileage: | 158409 | Power Kw: | 85 |
| Bodytype: | SUV | Body color: | Dark Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3123 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|-----------------------------|--------------------------|-------|--------------------------|
| | 225/50/17/95 V Steel | | | |
| Winter tyres: | Fr.L. | Bridgestone: 5 mm | Fr.R. | Bridgestone: 5 mm |
| | Re.L. | Bridgestone: 4 mm | Re.R. | Bridgestone: 4 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|-------|
| Total cost ex VAT | 60,00 |
|-------------------|-------|

| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---|-------|
| Wheel cover R R, Scratch(es), E - Replace | 30,00 |
|---|-------|



| | |
|-------------------------------|------|
| Wing R R, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

| | |
|---|-------|
| Wheel cover F R, Scratch(es), E - Replace | 30,00 |
|---|-------|

