



BMW SERIE 5: 1FKZ180			
Vinnumber:	WBAFW11030D270553	Versionname:	520dA
First Registrationdate:	1/08/2013	Fiscalpower:	
Expertise Mileage:	150354	Power Kw:	120
Bodytype:	Berline	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	SERVICE DANS 9000 KM	Parking lot:	2211
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Seats electric F L
GPS storage HD	Seats electric F R
GPS storage	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting Headlighting Xenon	
Type of GPS GPS big screen color	
Type of Lining Lining leather	
Type of climate control Autom climate control	
Level control	


Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	NOT OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	225/55/17/101 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment	
	Runflat Yes
Total cost ex VAT	3547,46
Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	312,21



Door F R, Scratch(es), LI - Repair and paint (complete)	382,02
---	---------------



Tailgate, Bump(s), LI - Repair and paint (complete) 410,02



Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Engine, Empty, P - Check 0,00



Sill trim R, Scratch(es), LI - Repair and paint (complete) 372,60



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Wing F R, Scratch(es), 67 - Polish 55,19



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 417,84



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 478,02



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00

