



|                         |                          |              |                         |
|-------------------------|--------------------------|--------------|-------------------------|
| <b>BMW 3: DB7986</b>    |                          |              |                         |
| Vinnumber:              | <b>WBA3D71040F147814</b> | Versionname: | <b>3 BER 325d 218PK</b> |
| First Registrationdate: | <b>8/12/2015</b>         | Fiscalpower: |                         |
| Expertise Mileage:      | <b>95832</b>             | Power Kw:    | <b>160</b>              |
| Bodytype:               |                          | Body color:  | <b>Dark Blue</b>        |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>          |
| Transmission:           |                          | Rims summer: | <b>Aluminium</b>        |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>               |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>2404</b>             |
| Number of doors:        | <b>4</b>                 |              |                         |
| Number of seats:        | <b>5</b>                 |              |                         |
| Number head rests:      | <b>5</b>                 |              |                         |
| Rims summer:            | <b>Aluminium</b>         |              |                         |
| Category:               | <b>Passenger Car</b>     |              |                         |
| Oil level:              | <b>OK</b>                |              |                         |

|                                |                              |
|--------------------------------|------------------------------|
| <b>Options</b>                 |                              |
| Radio CD                       | Sun Roof electric            |
| Windows electric F             | Central consol F             |
| Windows electric R             | Luggage cover                |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional |                              |
| Seats F heated                 |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting LED</b>      |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining leather</b>        |
| Type of climate control        | <b>Autom climate control</b> |

|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position                       | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission                        | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake                           | <b>OK</b> |                     |            |

|                       |                                  |                       |       |                       |
|-----------------------|----------------------------------|-----------------------|-------|-----------------------|
| <b>Degree of wear</b> |                                  |                       |       |                       |
|                       | <b>225/50/17/94 H LightMetal</b> |                       |       |                       |
| Winter tyres:         | Fr.L.                            | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|                       | Re.L.                            | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

|   |                |
|---|----------------|
| <b>Assistance equipment</b>   |                |
| Runflat   | <b>Yes</b>     |
| Total cost ex VAT   | <b>1945,00</b> |
| Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) | <b>308,20</b>  |






Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Roof, Bump(s), LI - Repair and paint (complete) 481,50



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35

