



FORD Transit 280S: 1ETO031

Vinnnumber:	WFOXXXTTFXDU73644	Versionname:	TRANSIT 280S B/F SWB Silv.DPF(EU5)100PK
First Registrationdate:	18/03/2013	Fiscalpower:	
Expertise Mileage:	251072	Power Kw:	74
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	TRU10
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD
Windows electric F
Cruise Control
Steering wheel multifunctional
Type of headlighting Headlighting Halogen
Type of Lining Lining fabrics
Type of climate control Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/70/15/104 R Steel			
Summer tyres:	Fr.L.	Bridgestone: 8 mm	Fr.R.	Bridgestone: 8 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Total cost ex VAT	2136,80
Wheel cover F L, Missing, E - Replace	22,50



Door moulding Lower R L, Scratch(es), E - Replace	91,50
---	-------



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	--------



Glove box cover, Damaged, Repair/replace (lump sum) 24,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 231,15



Interior, Dirty, Cleaning 50,00



Door moulding Lower F L, Missing, E - Replace 91,50



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15




Floor covering F L, Hole, E - Replace 237,00



Roof, Bump(s) and scratch(es), LI - Repair and paint (complete) 361,13



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76




Rearview mirror L complete, Damaged, E - Replace	138,00
--	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Seat cover F L, Worn, Acceptable	0,00
----------------------------------	------



Trunk door R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	158,85
---	--------



Wheel cover F R, Missing, E - Replace	22,50
---------------------------------------	-------

