


BMW X3: 1GBF974

Vinnnumber:	WBAWY310100F23563	Versionname:	X3 xDrive20 163PK Aut.
First Registrationdate:	13/12/2013	Fiscalpower:	
Expertise Mileage:	104246	Power Kw:	120
Bodytype:	SUV	Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2512
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/60/17/99 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	333,16
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Bump(s), LI - Repair and paint (complete)	254,16



Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Protection plate M, Tear, E - Replace	79,00



Bonnet, Bump(s), Acceptable

0,00

No pictures to display