



CITRO?N C4 Picasso: 1GED260			
Vinnnumber:	VF73A9HC8DJ880187	Versionname:	GR.C4 PICASSO Exclusive
First Registrationdate:	14/01/2014	Fiscalpower:	115PK
Expertise Mileage:	140078	Power Kw:	85
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2506
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Windows electric F		Seats electric F L	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	205/55/17/95 V LightMetal			
Winter tyres:	Fr.L.	Kleber: 7 mm	Fr.R.	Kleber: 7 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment	
Compressor	Yes
Total cost ex VAT	1542,56
Certificate Of Conformity, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Wing R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper grille, Damaged, E - Replace	104,00



Door R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Interior, Dirty, Cleaning 50,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 290,08



Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display