



**BMW 1: 1JLX383**

Vinnnumber:	<b>WBA1T91040P978598</b>	Versionname:	<b>1 BER HATCH 114d 95PK</b>
First Registrationdate:	<b>20/01/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>39135</b>	Power Kw:	<b>70</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3401</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Steering wheel multifunctional	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/55/16/91 MS Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>454,68</b>
Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>301,68</b>



Wheel cover F L, Scratch(es), Acceptable	<b>0,00</b>
------------------------------------------	-------------

No pictures to display

Wheel cover R L, Damaged, E - Replace	<b>30,00</b>
---------------------------------------	--------------



Wheel cover R R, Damaged, E - Replace	<b>30,00</b>
---------------------------------------	--------------



Roof, Bump(s), PDR - Knock out without painting 63,00



Wheel cover F R, Damaged, E - Replace 30,00



Wing R R, Bump(s), Acceptable 0,00

*No pictures to display*