


**BMW 5: 1DEZ547**

Vinnumber:	<b>WBAMX11020C975046</b>	Versionname:	<b>5 TOURING 520d</b>
First Registrationdate:	<b>26/04/2012</b>	Fiscalpower:	<b>Start/Stop 163PK</b>
Expertise Mileage:	<b>136568</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3311</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F
TV/DVD screen R		Luggage cover
GPS storage	<b>HD</b>	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>NOT OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**


	<b>225/55/17/97 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 6 mm</b>	Fr.R.	<b>Bridgestone: 6 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>657,32</b>
Rear window, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Interior, Dirty, Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Air vent R M, Damaged, E - Replace	<b>54,00</b>


**Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)**
**254,16**



Wing R L, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16



Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00

