



<b>BMW 3: 1FIH084</b>			
Vinnnumber:	<b>WBA3D11030F328464</b>	Versionname:	<b>3 BER 318d 136PK</b>
First Registrationdate:	<b>5/07/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>117519</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Berline</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2427</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>	
Radio CD	Rear parking sensors
GPS storage	<b>HD</b>
GPS storage	
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining artificial leather</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>225/45/18/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Pirelli: 3 mm</b>	Re.R.	<b>Pirelli: 3 mm</b>

<b>Assistance equipment</b>	
	<b>Runflat</b>
	<b>Yes</b>
Total cost ex VAT	<b>380,00</b>
Bumper R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Bumper F R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Seat cover F L, Tear, Acceptable	<b>0,00</b>



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Bad repair, Paint 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Bad repair, Paint 0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bad repair, Paint 0,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display