



**FORD MONDEO: 1EXR199**

Vinnumber:	<b>WF0GXXGBBGDU04702</b>	Versionname:	<b>MONDEO CLIP Econetic Trend 115PK</b>
First Registrationdate:	<b>16/04/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>115947</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>4731</b>
Maintenance:	<b>CONTROLLER</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>0/0/0/0 A Steel</b>			
Summer tyres:	Fr.L.	<b>N.D.</b>	Fr.R.	<b>N.D.</b>
	Re.L.	<b>N.D.</b>	Re.R.	<b>N.D.</b>
	<b>215/55/16/93 H Steel</b>			
Winter tyres:	Fr.L.	<b>Kleber: 7 mm</b>	Fr.R.	<b>Kleber: 7 mm</b>
	Re.L.	<b>Uniroyal: 7 mm</b>	Re.R.	<b>Uniroyal: 7 mm</b>









**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	3023,96
-------------------	---------

Interior, Dirty, Cleaning	100,00
---------------------------	--------



	Wheel cover R L, Missing, E - Replace	30,00
	Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	259,80
	Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	366,35
	Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
	Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	356,20
	Roof, Chemical pollution, LI - Repair and paint (complete)	481,50
	Door F L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>		
	Bonnet, Scratch(es), LI - Repair and paint (complete)	290,08



Door R R, Chemical polution, LI - Repair and paint (complete)	318,35
---	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

