

**AUDI A3: 1EMF064**

| | | | |
|-------------------------|--------------------------|--------------|--------------------------------|
| Vinnumber: | WAUZZZ8V1DA021552 | Versionname: | A3 BER Attraction 105PK |
| First Registrationdate: | 21/01/2013 | Fiscalpower: | |
| Expertise Mileage: | 109152 | Power Kw: | 77 |
| Bodytype: | Hatchback | Body color: | Dark Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2426 |
| Number of doors: | 3 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Steering wheel multifunctional | Front parking sensors |
| Seats F heated | Rear parking sensors |
| Radio multimedia | |
| Type of headlighting: | Headlighting Halogen |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining leather |
| Type of climate control: | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|----------------------|-------|----------------------|
| | 205/55/16/91 V LightMetal | | | |
| Summer tyres: | Fr.L. | Pirelli: 4 mm | Fr.R. | Pirelli: 4 mm |
| | Re.L. | Pirelli: 5 mm | Re.R. | Pirelli: 5 mm |

Assistance equipment

| | |
|-------------|------------|
| Spare wheel | Yes |
| Repair kit | Yes |

| | |
|---------------------------------------|--------|
| Total cost ex VAT | 648,20 |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Rear window, Scratch(es), E - Replace | 0,00 |



| | |
|--|-------|
| Wing R L 3P, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |



| | |
|------------------------------------|--------|
| Ignition key, Missing, E - Replace | 150,00 |
|------------------------------------|--------|

No pictures to display

| | |
|--|-------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



| | |
|---|--------|
| Wing R R, Scratch(es), LI - Repair and paint (complete) | 308,20 |
|---|--------|

