



BMW X1: 1ECM481			
Vinnumber:	WBAVY11000VW86513	Versionname:	X1 sDrive16 116PK
First Registrationdate:	19/10/2012	Fiscalpower:	
Expertise Mileage:	64674	Power Kw:	85
Bodytype:	SUV	Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2522
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	225/50/17/94 H Steel			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm


Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			321,80
Front bumper, Scratch(es), LI - Repair and paint (complete)			211,80



Interior, Dirty, Cleaning	50,00
---------------------------	--------------



Wheel cover R R, Scratch(es), E - Replace	30,00
---	--------------



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), E - Replace	30,00

