



BMW 3: 1EHE714			
Vinnnumber:	WBA3K91010F230747	Versionname:	3 TOURING 316d 116PK
First Registrationdate:	3/12/2012	Fiscalpower:	
Expertise Mileage:	132751	Power Kw:	85
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1525
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Semperit: 5 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	1475,05
Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35



Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display