



BMW 3: 1DNQ778			
Vinnumber:	WBA3D91090F402226	Versionname:	3 BER 316d 116PK
First Registrationdate:	2/07/2012	Fiscalpower:	
Expertise Mileage:	136570	Power Kw:	85
Bodytype:	Berline	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1719
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	205/60/16/96 H Steel			
Winter tyres:	Fr.L.	Fulda: 7 mm	Fr.R.	Fulda: 7 mm
	Re.L.	Fulda: 6 mm	Re.R.	Fulda: 6 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes

Total cost ex VAT	885,95
Steering wheel, Chemical polution, E - Replace	84,00






Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Door F R, Bump(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Wheel cover F R, Scratch(es), E - Replace	30,00
	
Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
	
Wheel cover R R, Scratch(es), E - Replace	30,00
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
