



BMW 6 Gran Coupe: 1EKN216

Vinnnumber:	WBA6A610X0DY87492	Versionname:	6 GRAN COUPE 640dA 313PK Aut.
First Registrationdate:	7/01/2013	Fiscalpower:	
Expertise Mileage:	174971	Power Kw:	230
Bodytype:		Body color	Light Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2523
Number of doors	4		
Number of seats	5		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Sun Roof electric	
Cruise Control		Central consol F	
Steering wheel multifunction		Front parking sensors	
Seats F heated		Rear parking sensors	
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	245/40/19/98 V LightMetal			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	2011,26
Door R L, Scratch(es), LI - Repair and paint (complete)	382,02



Front bumper, Scratch(es), It - Spot repair	115,56
---	---------------





Wing R L, Scratch(es), LI - Repair and paint (complete) 369,84



Alloy rim F R, Scratch(es), E - Replace 277,44



Alloy rim R L, Scratch(es), E - Replace 277,44



Bumper grille, Damaged, E - Replace 34,08



Alloy rim F L, Scratch(es), E - Replace 277,44



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), E - Replace 277,44

