



CITROEN C4 Picasso: 1HBV892

Vinnnumber:**VF73A9HC8EJ683592**

First Registrationdate:**13/06/2014**

Expertise Mileage:**181085**

Bodytype:**MPV**

Gearbox:**MAN 6 VIT**

Transmission:**Front**

Fueltype:**Diesel**

Battery functioning:**Yes**

Number of doors:**5**

Number of seats:**7**

Number head rests:**7**

Rims summer:**Aluminium**

Category:**Passenger Car**

Oil level:**OK**

Registration Certificate Car (BE):**Yes**

Versionname:**GR.C4 PICASSO Business**

Fiscalpower:**GPS 115PK**

Power Kw:**85**

Body color:**Dark Grey**

Paint type:**Metalic**

Rims summer:**Aluminium**

Oil level:**OK**

Parking lot:**2504**

Options

Radio CD

Windows electric F

Windows electric R

Cruise Control

Steering wheel multifunctional

Radio multimedia

Type of headlighting

Type of GPS

Type of Lining

Type of climate control

Luggage cover

Rear parking sensors

Type of Tow bar

Tow bar fixed

Limited Technical Inspection

Airco functioning

OK

Battery functioning

Yes

Tires wear profile

OK

Sound engine

OK

Idle position

OK

Clutch test

OK

Engine startingtime

OK

Wiper fluid level

OK

Exhaust gass

OK

Lighting

OK

Transmission

OK

Wiperblades

OK

Handbrake

OK

Degree of wear

Winter tyres:

205/60/16/92 H LightMetal

Fr.L.

Uniroyal: 4 mm

Fr.R.

Uniroyal: 4 mm

Re.L.

Uniroyal: 5 mm

Re.R.

Uniroyal: 5 mm

Assistance equipment

Spare tyre compact

Yes

Jack

Yes

Total cost ex VAT

115,56

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Rear window, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Bump(s), Acceptable

0,00

No pictures to display

Spoiler R, Scratch(es), LI - Repair and paint (complete)

115,56

Windscreen, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stain, Acceptable	0,00
<i>No pictures to display</i>	