



**FORD Focus: 1FQF762**

Vinnnumber:	<b>WF0KXXGCBKDR09482</b>	Versionname:	<b>FOCUS BER ECONetic Trend 88g 105PK</b>
First Registrationdate:	<b>23/09/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>152026</b>	Power Kw:	<b>77</b>
Bodytype:		Body color	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3824</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Luggage cover	
GPS storage	<b>SD</b>	Rear parking sensors	
GPS storage			
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/55/16/91 T Steel</b>			
Winter tyres:	Fr.L.	<b>BF Goodrich: 4 mm</b>	Fr.R.	<b>BF Goodrich: 4 mm</b>
	Re.L.	<b>BF Goodrich: 4 mm</b>	Re.R.	<b>BF Goodrich: 4 mm</b>

**Assistance equipment**











Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>1006,78</b>
-------------------	----------------

Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>220,18</b>
---------------------------------------------------------------------	---------------



Wing R L, Bump(s), Acceptable	<b>0,00</b>
-------------------------------	-------------

		Door F L, Bump(s), Acceptable	0,00
		Wheel cover R L, Scratch(es), E - Replace	30,00
		Door seal R L, Damaged, E - Replace	54,00
		Wheel cover F L, Scratch(es), E - Replace	30,00
		Door R L, Bump(s), Acceptable	0,00
		Door F R, Bump(s), PDR - Knock out without painting	63,00
		Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
		Wing R R, Bump(s), Acceptable	0,00
		Door F R, Bump(s), Acceptable	0,00



Floor covering F L, Worn, P - Check 0,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Bump(s), PDR - Knock out without painting 63,00



Wing R L, Bump(s), PDR - Knock out without painting 63,00



Wheel cover F R, Scratch(es), E - Replace 30,00

