


FORD Mondeo: 1GAD566

Vinnumber:	WF0GXXGBBGDD88362	Versionname:	MONDEO CLIP ECONetic Trend Style 115PK
First Registrationdate:	4/12/2013	Fiscalpower:	
Expertise Mileage:	107395	Power Kw:	85
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3308
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Front parking sensors
GPS storage	SD	Rear parking sensors
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	397,00
-------------------	--------

Luggage space cover, Missing, E - Replace	50,00
---	-------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Floor covering F L, Hole, E - Replace	252,00
---------------------------------------	--------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------



Door R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bonnet, Bump(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

No pictures to display

Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display