



CITROEN C5: 1FNJ595

Vinnumber:	VF7RDRHR8DL516662	Versionname:	C5 BER Business GPS FAP
First Registrationdate:	28/08/2013	Fiscalpower:	136PK
Expertise Mileage:	61761	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	GEEN MELDING	Parking lot:	1212
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Rear parking sensors	
GPS storage		Type of Tow bar	Tow bar removable
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	225/55/17/101 V LightMetal			
Winter tyres:	Fr.L.	Firestone: 8 mm	Fr.R.	Firestone: 8 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1019,80
-------------------	----------------

Moulding windscreen R, Unclapsed, N - Fit/Remove	10,00
--	--------------



Maintenance, Maintenance, P - Check	0,00
-------------------------------------	-------------



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Interior, No damage, Acceptable 0,00



Roof, Bump(s), PDR - Knock out without painting 538,20



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s), LI - Repair and paint (complete) 259,80



Tailgate, Bump(s), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display