



**IVECO DAILY: 1RJA593**

|                                    |                                 |              |               |
|------------------------------------|---------------------------------|--------------|---------------|
| Vinnumber:                         | <b>ZCFC235B405134377</b>        | Versionname: |               |
| First Registrationdate:            | <b>3/01/2017</b>                | Fiscalpower: |               |
| Expertise Mileage:                 | <b>42221</b>                    | Power Kw:    | <b>115</b>    |
| Bodytype:                          | <b>Transporter</b>              | Body color:  | <b>White</b>  |
| Gearbox:                           | <b>MAN 6 VIT</b>                | Paint type:  | <b>Opaque</b> |
| Transmission:                      | <b>Back</b>                     | Rims summer: | <b>Steel</b>  |
| Fueltype:                          | <b>Diesel</b>                   | Oil level:   | <b>OK</b>     |
| Battery functioning:               | <b>Yes</b>                      | Parking lot: | <b>LCV15</b>  |
| Number of doors:                   | <b>4</b>                        |              |               |
| Number of seats:                   | <b>7</b>                        |              |               |
| Number head rests:                 | <b>7</b>                        |              |               |
| Rims summer:                       | <b>Steel</b>                    |              |               |
| Category:                          | <b>Light Commercial Vehicle</b> |              |               |
| Oil level:                         | <b>OK</b>                       |              |               |
| Registration Certificate Car (BE): | <b>Yes</b>                      |              |               |

**Options**

|                                |                                  |                      |
|--------------------------------|----------------------------------|----------------------|
| Radio CD                       | Type of Tow bar                  | <b>Tow bar fixed</b> |
| Windows electric F             |                                  |                      |
| Steering wheel multifunctional |                                  |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>      |                      |
| Type of Lining                 | <b>Lining artificial leather</b> |                      |
| Type of climate control        | <b>Manual climate control</b>    |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position       | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission        | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake           | <b>OK</b> |                     |            |

**Degree of wear**

|               |                              |                    |       |                    |
|---------------|------------------------------|--------------------|-------|--------------------|
|               | <b>195/75/16/108 T Steel</b> |                    |       |                    |
| Summer tyres: | Fr.L.                        | <b>Other: 5 mm</b> | Fr.R. | <b>Other: 5 mm</b> |
|               | Re.L.                        | <b>Other: 4 mm</b> | Re.R. | <b>Other: 4 mm</b> |

**Assistance equipment**

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

|                          |               |
|--------------------------|---------------|
| <b>Total cost ex VAT</b> | <b>339,20</b> |
|--------------------------|---------------|

|  |               |
|--|---------------|
| <b>Front bumper, Scratch(es), Smart repair</b> | <b>110,64</b> |
|--|---------------|



|  |               |
|--|---------------|
| <b>Sidewalll RR (LCV), Scratch(es), It - Spot repair</b> | <b>115,56</b> |
|--|---------------|



|  |              |
|--|--------------|
| <b>Wing F L, Bump(s), PDR - Knock out without painting</b> | <b>63,00</b> |
|--|--------------|



Interior, Dirty, Cleaning

50,00

