



DisA 3940.1 kW  
522 18"  
10-18

**IVECO Daily 29L9V: 1DTL463**

Vinnnumber:	<b>ZCFC297400D478227</b>	Versionname:	<b>DAILY 29L B/F SWB HR 29L11V (EU5)106PK</b>
First Registrationdate:	<b>22/08/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>52219</b>	Power Kw:	<b>78</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>Green</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV29</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD  
Windows electric F  
Cruise Control  
Type of headlighting **Headlighting Halogen**  
Type of Lining **Lining fabrics**

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>215/65/16/109 R Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 2 mm</b>	Re.R.	<b>Michelin: 2 mm</b>

**Assistance equipment**

Spare wheel **Yes**

Total cost ex VAT	228,00
Glove box cover, Damaged, E - Replace	228,00



Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display