


MERCEDES B: 1CQG789

Vinnumber:	WDD2462001J018467	Versionname:	B 180 CDI BE 109PK
First Registrationdate:	1/02/2012	Fiscalpower:	
Expertise Mileage:	141748	Power Kw:	80
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4715
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover
GPS storage	
GPS storage	HD
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	713,47
-------------------	---------------

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	-------------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Seat cover F L, Stain, Forfeit	12,00
--------------------------------	--------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bump(s), LI - Repair and paint (complete) 318,35



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover F R, Stain, Forfeit 12,00



Backrest cover F L, Scratch(es), Smart repair 64,32



Door R R, Bump(s), Acceptable 0,00

No pictures to display