


OPEL Insignia: 1EMR981

Vinnumber:	WOLGT8EL3D1056472	Versionname:	INSIGNIA BRE ecofl.Cosmo S/S DPF
First Registrationdate:	24/01/2013	Fiscalpower:	130PK
Expertise Mileage:	129533	Power Kw:	96
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4606
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	245/45/18/92 MS LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	374,64
Door panel R L, Scratch(es), Smart repair	110,64



Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror L complete, Unclasp(ed), N - Fit/Remove	12,00



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------



Protection plate M, Tear, E - Replace	62,00
---------------------------------------	-------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Rear window, Scratch(es), E - Replace	0,00
---------------------------------------	------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

No pictures to display