


OPEL Astra: 1FSJ019

Vinnnumber:	W0LPD8EW2D8076386	Versionname:	ASTRA BRE ecoFL Enjoy Active St/St 110PK
First Registrationdate:	9/10/2013	Fiscalpower:	
Expertise Mileage:	111898	Power Kw:	81
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2612
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
GPS storage	SD	Rear parking sensors	
GPS storage		Type of Tow bar	Tow bar removable
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/60/16/99 H Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm


Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	435,64
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Inner door handle F L, Scratch(es), Acceptable	0,00



Bonnet, Bump(s), LI - Repair and paint (complete)	290,08
---	--------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover F R, Scratch(es), E - Replace	30,00
---	-------



Front bumper, Scratch(es), It - Spot repair	115,56
---	--------

