


**PEUGEOT 508: 1DRH488**

Vinnnumber:	<b>VF38DRHR8CL060859</b>	Versionname:	<b>508 BER Active 136PK</b>
First Registrationdate:	<b>1/08/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>144688</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3307</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		
Head-up Display			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

215/60/16/99 H LightMetal				
Winter tyres:	Fr.L.	<b>Kleber: 5 mm</b>	Fr.R.	<b>Kleber: 5 mm</b>
	Re.L.	<b>Kleber: 4 mm</b>	Re.R.	<b>Kleber: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>343,35</b>
Wing R L, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Roof, Bump(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Bumper corner R R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Seat cover F R, Dirty, Cleaning			<b>25,00</b>



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F L, Scratch(es), Acceptable

0,00

*No pictures to display*