


**OPEL INSIGNA ST: 1ELH559**

Vinnumber:	<b>WOLGT8EL6D1049113</b>	Versionname:	<b>ecofl.Cosmo S/S DPF</b>
First Registrationdate:	<b>14/01/2013</b>	Fiscalpower:	<b>130PK</b>
Expertise Mileage:	<b>163826</b>	Power Kw:	<b>96</b>
Bodytype:		Body color	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>2413</b>
Maintenance	<b>OLIE + 59%</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD		Seats electric F L
GPS storage		Seats electric F R
GPS storage	<b>SD</b>	Sun Roof electric
Windows electric F		Panoramic roof
Windows electric R		Central consol F
Cruise Control		Luggage cover
Steering wheel multifunctional		Front parking sensors
Seats F heated		Rear parking sensors
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	
Level control		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>NOT OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>225/55/17/97 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 7 mm</b>	Fr.R.	<b>Michelin: 7 mm</b>
	Re.L.	<b>Uniroyal: 5 mm</b>	Re.R.	<b>Uniroyal: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	1688,68
-------------------	---------

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 414,35



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 268,18



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 414,35



Door R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display