



<b>NISSAN Qashqai: 1HFB582</b>			
Vinnnumber:	<b>SJNFAAJ11U1131760</b>	Versionname:	<b>QASHQAI 2WD Tekna 110PK</b>
First Registrationdate:	<b>4/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>87790</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>NOT OK</b>
Battery functioning:	<b>No</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>NOT OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

<b>Options</b>			
Type of headlighting:	<b>Headlighting Halogen</b>	Front parking sensors:	
Type of Lining:	<b>Lining artificial leather</b>	Rear parking sensors:	

<b>Limited Technical Inspection</b>			
Airco functioning:	<b>NOT OK</b>	Battery functioning:	<b>No</b>
Tires wear profile:	<b>NOT OK</b>	Sound engine:	<b>NOT OK</b>
Idle position:	<b>NOT OK</b>	Clutch test:	<b>NOT OK</b>
Engine startingtime:	<b>NOT OK</b>	Wiper fluid level:	<b>NOT OK</b>
Exhaust gass:	<b>NOT OK</b>	Lighting:	<b>NOT OK</b>
Transmission:	<b>NOT OK</b>	Wiperblades:	<b>NOT OK</b>
Handbrake:	<b>NOT OK</b>		

<b>Degree of wear</b>				
	<b>225/45/19/92 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Dunlop: 5 mm</b>	Fr.R.	<b>Dunlop: 5 mm</b>
	Re.L.	<b>Dunlop: 6 mm</b>	Re.R.	<b>Dunlop: 6 mm</b>

<b>Assistance equipment</b>			
Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>

<b>Total cost ex VAT</b>	<b>0,00</b>
<b>Bodywork, Accident, No repair</b>	<b>0,00</b>



