


MINI Clubman: 1FRK080

Vinnnumber:	WMWZH11060T357540	Versionname:	MINI CLUBMAN One D
First Registrationdate:	1/10/2013	Fiscalpower:	90PK DPF
Expertise Mileage:	89683	Power Kw:	66
Bodytype:		Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1224
Maintenance:	SERVICE IN 10000KM 8		
	2018		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
GPS storage	HD	Rear parking sensors	
GPS storage			
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS portable		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	NOT OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	175/65/15/84 T LightMetal			
Winter tyres:	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

 Runflat **No**


























 Total cost ex VAT **1076,64**

 Bumper R, Scratch(es), LI - Repair and paint (complete) **211,80**

 Trunk door R L, Bump(s), Acceptable **0,00**
No pictures to display

 Door F L, Bump(s) and scratch(es), Acceptable **0,00**
No pictures to display

 Alloy rim F R, Scratch(es), LI - Repair and paint (complete) **95,00**

			Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
			Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
			Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
			Trunk door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
			Bumper spoiler F, Scratch(es), E - Replace	42,00
			Reflector, Broken, E - Replace	29,60
			Wing moulding F R, Scratch(es), E - Replace	14,40
			Ignition key, Damaged, Acceptable	0,00
<i>No pictures to display</i>				
			Molding trunk, Scratch(es), E - Replace	67,96
			Wing R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>				
			Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	290,08
				
				
			Sill trim R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
			Rearlight R, Broken, E - Replace	114,00
				

Foglight L, Not functioning (well), P - Check 0,00



Windscreen, Stone chip(s), P - Check 0,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Tires, Not original part, P - Check 0,00



GPS, Not original part, P - Check 0,00

