



VOLKSWAGEN Golf: 1ELI328			
Vinnnumber:	<b>WVWZZZ1KZDW114836</b>	Versionname:	<b>GOLF BER BlueMotion DPF 105PK</b>
First Registrationdate:	<b>14/01/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>151700</b>	Power Kw:	<b>77</b>
Bodytype:		Body color	<b>Light Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>1225</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear			
Winter tyres:	<b>195/65/15/91 H LightMetal</b>		
	Fr.L.	Fr.R.	
	<b>Uniroyal: 5 mm</b>	<b>Uniroyal: 5 mm</b>	
	Re.L.	Re.R.	
	<b>Bridgestone: 3 mm</b>	<b>Bridgestone: 3 mm</b>	

Assistance equipment			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			305,56
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)			95,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

