



PEUGEOT BOXER : 1HZF635

Vinnumber:	VF3YCTMFC12679566	Versionname:	
First Registrationdate:	5/11/2014	Fiscalpower:	
Expertise Mileage:	49135	Power Kw:	96
Bodytype:	Transporter	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV19
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	215/70/15/109 S Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 2842,57

Rearview mirror R complete, Damaged, E - Replace	138,00
--	--------



Bumper corner R L, Crack, Smart repair	110,64
--	--------



Wheel cover R R, Missing, E - Replace	22,50
---------------------------------------	-------



Rearview mirror L complete, Damaged, E - Replace 138,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 238,76



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 165,13



Fuel cap cover, Damaged, E - Replace 49,00




Wheel cover F R, Missing, E - Replace 22,50



Front bumper, Bump(s) and scratch(es), Smart repair 110,64



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15





Roof, Bump(s) and scratch(es), LI - Repair and paint (complete) 361,13



Interior, Dirty, Cleaning 100,00



Sliding door R, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Wheel cover F L, Missing, E - Replace 22,50



Roof pillar R, Scratch(es), It - Spot repair 115,56



Wing F R, Hole, LI - Repair and paint (complete) 165,13

