



OPEL Zafira: 1FLQ771

Vinnumber:	WOLPE9E37D2106011	Versionname:	ZAFIRA TOURER
First Registrationdate:	8/08/2013	Fiscalpower:	ecoFL.Cosmo S/S 136PK
Expertise Mileage:	75944	Power Kw:	100
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2119
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage		Front parking sensors	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		


Degree of wear

	225/50/17/94 V LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	0,00
Door F R, Scratch(es), LI - Repair and paint (complete)	0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	0,00
--	------



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), Le - Replace and paint 0,00



Internal Boot Lining R, Scratch(es), Smart repair 0,00



Interior, Dirty, Cleaning 0,00



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Instruction book, Missing, E - Replace 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Smart repair 0,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00





Luggage space cover, Missing, E - Replace	0,00
---	------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display