



MERCEDES GLE COUPE: 1LED376

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnumber: | WDC2923241A007293 | Versionname: | 3.0 GLE 350 D 4MATIC |
| First Registrationdate: | 3/09/2015 | Fiscalpower: | |
| Expertise Mileage: | 66785 | Power Kw: | 190 |
| Bodytype: | SUV | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2306 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|----------------------|
| Radio CD | | Seats electric F L | |
| Windows electric F | | Seats electric F R | |
| Windows electric R | | Central consol F | |
| Cruise Control | | Front parking sensors | |
| Steering wheel multifunctional | | Rear parking sensors | |
| Radio multimedia | | Type of Tow bar | Tow bar fixed |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|-----------------------------------|--------------------------|-------|--------------------------|
| | 275/45/21/110 Y LightMetal | | | |
| Summer tyres: | Fr.L. | Continental: 3 mm | Fr.R. | Continental: 3 mm |
| | Re.L. | Continental: 5 mm | Re.R. | Continental: 5 mm |

Assistance equipment

| | |
|--|--------|
| Total cost ex VAT | 457,02 |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |



| | |
|---|--------|
| Tailgate, Scratch(es), LI - Repair and paint (complete) | 362,02 |
|---|--------|

