



<b>RENAULT Grand Scenic: 1FMR226</b>			
Vinnumber:	<b>VF1JZ14M649513862</b>	Versionname:	<b>GRAND SCENIC Expression Spl.110PK</b>
First Registrationdate:	<b>21/08/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>43999</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2712</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>205/60/16/96 H Steel</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

<b>Assistance equipment</b>			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>

<b>Total cost ex VAT</b>	<b>1007,74</b>
<b>Front bumper, Scratch(es), LI - Repair and paint (complete)</b>	<b>211,80</b>



<b>Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>310,50</b>
--	---------------



<b>Wheel cover F R, Scratch(es), E - Replace</b>	<b>30,00</b>
--	--------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Dashboard, Scratch(es), Smart repair 110,64



Rearview mirror housing L, Broken, E - Replace 84,00



Reflector, Damaged, E - Replace 49,00

