


**OPEL ASTRA: 1DDI352**

Vinnnumber:	<b>W0LPD8EW8C8080327</b>	Versionname:	
First Registrationdate:	<b>16/04/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>97304</b>	Power Kw:	
Bodytype:	<b>Break</b>	Body color:	<b>Green</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4124</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
GPS storage			
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>215/60/16/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 2 mm</b>	Fr.R.	<b>Continental: 2 mm</b>
	Re.L.	<b>Continental: 2 mm</b>	Re.R.	<b>Continental: 2 mm</b>

**Assistance equipment**

Spare tyre compact	<b>Yes</b>	Jack	<b>Yes</b>
--------------------	------------	------	------------

Total cost ex VAT	0,00
-------------------	------

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Seat cover F L, Stain, Acceptable	0,00
-----------------------------------	------

*No pictures to display*