



RENAULT Grand Scenic: 1EPP151			
Vinnnumber:	VF1JZ14A648308072	Versionname:	GR.SCENIC Energ.Bose Edit.5pl.FAP 110PK
First Registrationdate:	15/02/2013	Fiscalpower:	
Expertise Mileage:	170256	Power Kw:	81
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1713
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	205/55/17/95 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm


Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1405,58
Windscreen, Repaired, Acceptable			0,00



Seat cover F L, Worn, Acceptable	0,00
---	-------------



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
--	---------------



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete) 310,50

