


**RENAULT Espace: 1FSU328**

Vinnumber:	<b>VF1JKFJAC49610936</b>	Versionname:	<b>ESPACE Alcantara 149PK Aut.</b>
First Registrationdate:	<b>14/10/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>161981</b>	Power Kw:	<b>110</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2724</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	<b>SD</b>	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>Tow bar removable</b>
Seats F heated			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining artificial leather and alcantara</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

Winter tyres:	<b>225/55/17/101 V LightMetal</b>			
	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	2157,91
-------------------	---------

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Internal Boot Lining L, Damaged, E - Replace	99,00
--	-------



Windscreen, Damaged, E - Replace	0,00
----------------------------------	------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Tear, Acceptable 0,00



Backrest cover R M, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00




Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Alloy rim F L, Damaged, E - Replace 277,44



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 382,02



Roof pillar R, Scratch(es), LI - Repair and paint (complete) 264,22



Wing F R, Scratch(es), LI - Repair and paint (complete) 264,21



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bump(s), LI - Repair and paint (complete) 382,02



Internal Boot Lining R, Damaged, E - Replace 149,00

