



**PEUGEOT Bipper: 1EEN481**

Vinnnumber:	<b>VF3AAFHZ0C8291475</b>	Versionname:	<b>BIPPER B/F FAP(EU5)</b>
First Registrationdate:	<b>8/11/2012</b>	Fiscalpower:	<b>75pk</b>
Expertise Mileage:	<b>150113</b>	Power Kw:	<b>55</b>
Bodytype:		Body color	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3105</b>
Number of doors	<b>4</b>		
Number of seats	<b>2</b>		
Number head rests	<b>2</b>		
Rims summer	<b>Steel</b>		
Category	<b>Light Commercial Vehicle</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD	Rear parking sensors
Windows electric F	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>

**Limited Technical Inspection**

Tires wear profile	<b>OK</b>	Battery functioning	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Transmission	<b>OK</b>	Lighting	<b>NOT OK</b>
Handbrake	<b>OK</b>	Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/65/15/88 H Steel</b>			
Summer tyres:	Fr.L.	<b>Dunlop: 3 mm</b>	Fr.R.	<b>Dunlop: 3 mm</b>
	Re.L.	<b>Dunlop: 7 mm</b>	Re.R.	<b>Dunlop: 7 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------




Total cost ex VAT	<b>1752,00</b>
Rearview mirror housing L, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>303,15</b>



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>351,15</b>
---	---------------



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>351,15</b>
---	---------------

	Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	351,15
	Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>		
	Windscreen, Broken, E - Replace	395,40
	Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		