



VOLVO V40: 1ELD569

| | | | |
|-------------------------|--------------------------|--------------|--------------------------|
| Vinnnumber: | YV1MV8481D2032260 | Versionname: | V40 D2 Base 115PK |
| First Registrationdate: | 11/01/2013 | Fiscalpower: | |
| Expertise Mileage: | 84164 | Power Kw: | 84 |
| Bodytype: | Break | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3425 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS portable |
| Type of Lining | Lining semi-leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|---------------------|-------|---------------------|
| | 205/55/16/91 V LightMetal | | | |
| Winter tyres: | Fr.L. | Dunlop: 6 mm | Fr.R. | Dunlop: 6 mm |
| | Re.L. | Dunlop: 7 mm | Re.R. | Dunlop: 7 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 211,80 |
|-------------------|---------------|

| | |
|-----------------------------------|-------------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

| | |
|---|---------------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|---------------|



| | |
|--|-------------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
|--|-------------|

No pictures to display