



VOLVO V60: 1FRG524

Vinnnumber:	YV1FW8481E1161781	Versionname:	V60 BRE D2 Kinetic 115PK
First Registrationdate:	1/10/2013	Fiscalpower:	
Expertise Mileage:	187699	Power Kw:	84
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3826
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/60/16/96 W LightMetal			
Summer tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
		Runflat	Yes

Total cost ex VAT	177,80
Bonnet, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Bump(s), PDR - Knock out without painting	82,80



Alloy rim F R, Scratch(es), Acceptable	0,00
--	-------------

<i>No pictures to display</i>	
Backrest cover F L, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Floor covering F L, Damaged, Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00

