



VOLKSWAGEN Caddy: 1JEJ073

Vinnnumber:	WV2ZZZ2KZFX050501	Versionname:	CADDY MAXI LIFE
First Registrationdate:	25/11/2014		Trendl.102PK OMBOUW
Expertise Mileage:	190901		Dub.
Bodytype:		Fiscalpower:	
Gearbox:	MAN 5 VIT	Power Kw:	75
Transmission:	Front	Body color	Grey
Fueltype:	Diesel	Paint type	Metalic
Maintenance	BINNEN 4700KM	Rims summer	Steel
Maintenance	NOT OK	Oil level	OK
Battery functioning	Yes	Parking lot	4301
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/94 H Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Total cost ex VAT	2178,04
Door trim F R, Deformed, E - Replace	91,50



Bonnet, Bump(s), LI - Repair and paint (complete)	280,88
---	--------



Front bumper, Deformed, E - Replace	398,40
-------------------------------------	--------



Wheel cover R R, Damaged, E - Replace 22,50



Brand badge, Missing, E - Replace 25,00



Wheel cover F R, Damaged, E - Replace 22,50



Door F R, Bump(s), Le - Replace and paint 847,88



Wheel cover F L, Damaged, E - Replace 22,50



Maintenance, Maintenance, P - Check 0,00



Wheel cover R L, Broken, E - Replace 22,50



Sill outer R, Bump(s), LI - Repair and paint (complete) 328,88



Foglight R, Broken, E - Replace 115,50

