



VOLKSWAGEN Passat: 1DCS611

| | | | |
|-------------------------|--------------------------|--------------|---|
| Vinnnumber: | WVWZZZ3CZCE150006 | Versionname: | PASSAT VAR Comfortline BMT 105PK |
| First Registrationdate: | 11/04/2012 | Fiscalpower: | |
| Expertise Mileage: | 102309 | Power Kw: | 77 |
| Bodytype: | Break | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1433 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Sun Roof electric |
| Windows electric F | Panoramic roof |
| Windows electric R | Central consol F |
| Cruise Control | Luggage cover |
| Steering wheel multifunctional | Front parking sensors |
| Seats F heated | Rear parking sensors |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 215/55/16/91 V LightMetal | | | |
| Summer tyres: | Fr.L. | Bridgestone: 4 mm | Fr.R. | Bridgestone: 4 mm |
| | Re.L. | Bridgestone: 5 mm | Re.R. | Bridgestone: 5 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 318,35 |
|-------------------|---------------|

| | |
|-----------------------------------|-------------|
| Door F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

| | |
|-----------------------------------|-------------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

| | |
|---|---------------|
| Door F L, Scratch(es), LI - Repair and paint (complete) | 318,35 |
|---|---------------|



| | |
|-------------------------------|-------------|
| Door R R, Bump(s), Acceptable | 0,00 |
|-------------------------------|-------------|

No pictures to display