



VOLVO V60: 1GER414

Vinnnumber:	YV1FW8481E1180238	Versionname:	V60 BRE D2 Kinetic 115PK
First Registrationdate:	17/01/2014	Fiscalpower:	
Expertise Mileage:	171143	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3728
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/96 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1777,00
-------------------	----------------

Roof, Scratch(es), 67 - Polish	55,19
--------------------------------	--------------



Seat cover R R, Bad repair, P - Check	0,00
---------------------------------------	-------------



Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Door R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s), LI - Repair and paint (complete) 452,20



Wing F L, Bump(s), PDR - Knock out without painting 63,00



Wing F R, Scratch(es), 67 - Polish 55,19



Door panel R L, Hole, E - Replace 114,00



Door panel F L, Hole, E - Replace 114,00




Door F R, Bump(s), LI - Repair and paint (complete) 366,35



Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bodywork, Dirty, P - Check	0,00
<i>No pictures to display</i>	
Spoiler roof, Scratch(es), 67 - Polish	55,19

