


RENAULT Clio: XP4377

Vinnnumber:	VF15RRL0H49590005	Versionname:	CLIO IV BER Dynamique St&St 90PK
First Registrationdate:	3/12/2013	Fiscalpower:	
Expertise Mileage:	153826	Power Kw:	66
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1715
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/55/16/87 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Jack	Yes
------	------------

Total cost ex VAT	1865,18
Wing F R, Chemical polution, LI - Repair and paint (complete)	176,14



Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	241,34



Bonnet, Chemical polution, LI - Repair and paint (complete) 232,06



Wing R L, Scratch(es), LI - Repair and paint (complete) 246,56



Interior, Dirty, Cleaning 100,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Damaged, E - Replace 50,00



Roof, Chemical polution, LI - Repair and paint (complete) 385,20



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Front bumper - Scratch(es), LI - Repair and paint (complete) 169,44

