



VOLVO V40: 1EHZ709

Vinnnumber:	YV1MV8481D2027472	Versionname:	V40 D2 Base 115PK
First Registrationdate:	10/12/2012	Fiscalpower:	
Expertise Mileage:	126416	Power Kw:	84
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1509
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining semi-artificial leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	205/55/16/91 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	211,80
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display