



MERCEDES Vito: 1HTP607			
Vinnnumber:	WDF63960313903211	Versionname:	VITO 113 B/F MWB A2 MyTool Ed.136PK
First Registrationdate:	30/09/2014	Fiscalpower:	
Expertise Mileage:	261016	Power Kw:	100
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1623
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	
Windows electric F	
Cruise Control	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	195/65/16/104 T Steel			
Summer tyres:	Fr.L.	Semperit: 8 mm	Fr.R.	Semperit: 8 mm
	Re.L.	Semperit: 9 mm	Re.R.	Semperit: 9 mm

Assistance equipment	
Spare wheel	Yes


Total cost ex VAT	1916,92
Seat cover F R, Damaged, E - Replace	300,00



Bonnet, Bump(s), PDR - Knock out without painting	63,00
---	-------



Front bumper, Broken, E - Replace	398,40
-----------------------------------	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Seat cover F L, Damaged, E - Replace	300,00
--------------------------------------	--------



Roof, Bump(s), Acceptable	0,00
---------------------------	------

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)	238,76
---	--------



Door F R, Bump(s), LI - Repair and paint (complete)	238,76
---	--------



Glove box cover, Damaged, E - Replace	228,00
---------------------------------------	--------



Trunk door R R, Bump(s), Acceptable	0,00
-------------------------------------	------

No pictures to display

Windscreen, Tear, E - Replace	0,00
-------------------------------	------

