



AUDI Q7: 1KDY638

Vinnnumber:	WAUZZZ4L7FD023845	Versionname:	
First Registrationdate:	10/04/2015	Fiscalpower:	
Expertise Mileage:	62120	Power Kw:	180
Bodytype:	MPV	Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2433
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	275/45/20/110 Y LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Spare tyre compact **Yes**

Total cost ex VAT **3160,37**

Door F R, Scratch(es), Acceptable **0,00**

No pictures to display

Bonnet, Chemical polution, Acceptable **0,00**

No pictures to display

Interior, Dirty, Cleaning **50,00**





Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Ignition key, Missing, E - Replace 150,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 382,02



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Wing R L, Scratch(es), LI - Repair and paint (complete) 369,84



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Bump(s) and scratch(es), Le - Replace and paint 1107,49



Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84

