



AUDI Q5: 1FOW236			
Vinnumber:	<b>WAUZZZ8R7EA029353</b>	Versionname:	<b>Q5 136PK</b>
First Registrationdate:	<b>10/09/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>108287</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1229</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Type of headlighting:	<b>Headlighting Xenon</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Autom climate control</b>
	Rear parking sensors

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

Degree of wear				
Summer tyres:	<b>235/65/17/104 H LightMetal</b>			
	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

Assistance equipment	
Spare tyre compact	<b>Yes</b>
Compressor	<b>Yes</b>

Total cost ex VAT	662,30
Door R R, Bump(s), Acceptable	0,00

<i>No pictures to display</i>	
Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09



Wing F L, Scratch(es), LI - Repair and paint (complete)	264,21
---	--------



Interior, Dirty, Cleaning	50,00
---------------------------	-------

