



BMW X1: 1DMQ388			
Vinnnumber:	WBAVZ91010VT50137	Versionname:	X1 sDrive20 Eff.Dyn.Edit 163PK
First Registrationdate:	25/06/2012	Fiscalpower:	
Expertise Mileage:	73909	Power Kw:	120
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1329
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	225/50/17/94 H LightMetal			
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment	
Runflat	Yes
Total cost ex VAT	1443,97
Door R L, Scratch(es), LI - Repair and paint (complete)	318,35



Interior, Dirty, Cleaning	50,00
---------------------------	--------------





Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), Smart repair 110,64



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), It - Spot repair 115,56



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

