



BMW 5: UM6634

Vinnumber:	WBA5B91060D566267	Versionname:	5 BER 520dXA 184PK Aut.
First Registrationdate:	16/01/2014	Fiscalpower:	
Expertise Mileage:	130155	Power Kw:	135
Bodytype:	Berline	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3408
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear



	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 2 mm	Fr.R.	Bridgestone: 2 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Total cost ex VAT	760,65
Door R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09
	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Air vent R M, Broken, E - Replace	158,40
	
Wing R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	